





TABELA ROZMIARÓW:
LIGHT GOLD

SYMBOL	DRZWI	WYMIAR	SZKŁO	A	B	W	H	X1*	X2*
K-1827	1	70x70x195	czyste 6mm	68,7-70,2	68,5-70	60	195	67,7-69,2	67,2-68,7
K-1828	1	70x80x195	czyste 6mm	68,7-70,2	78,5-80	60	195	67,7-69,2	77,2-78,7
K-1829	1	70x90x195	czyste 6mm	68,7-70,2	88,5-90	60	195	67,7-69,2	87,2-88,7
K-1830	1	70x100x195	czyste 6mm	68,7-70,2	98,5-100	60	195	67,7-69,2	97,2-98,7
K-1831	1	70x110x195	czyste 6mm	68,7-70,2	108,5-110	60	195	67,7-69,2	107,2-108,7
K-1832	1	70x120x195	czyste 6mm	68,7-70,2	118,5-120	60	195	67,7-69,2	117,2-118,7
K-1833	1	80x70x195	czyste 6mm	78,7-80,2	68,5-70	70	195	77,7-79,2	67,2-68,7
K-1834	1	80x80x195	czyste 6mm	78,7-80,2	78,5-80	70	195	77,7-79,2	77,2-78,7
K-1835	1	80x90x195	czyste 6mm	78,7-80,2	88,5-90	70	195	77,7-79,2	87,2-88,7
K-1836	1	80x100x195	czyste 6mm	78,7-80,2	98,5-100	70	195	77,7-79,2	97,2-98,7
K-1837	1	80x110x195	czyste 6mm	78,7-80,2	108,5-110	70	195	77,7-79,2	107,2-108,7
K-1838	1	80x120x195	czyste 6mm	78,7-80,2	118,5-120	70	195	77,7-79,2	117,2-118,7
K-1839	1	90x70x195	czyste 6mm	88,7-90,2	68,5-70	80	195	87,7-89,2	67,2-68,7
K-1840	1	90x80x195	czyste 6mm	88,7-90,2	78,5-80	80	195	87,7-89,2	77,2-78,7
K-1841	1	90x90x195	czyste 6mm	88,7-90,2	88,5-90	80	195	87,7-89,2	87,2-88,7
K-1842	1	90x100x195	czyste 6mm	88,7-90,2	98,5-100	80	195	87,7-89,2	97,2-98,7
K-1843	1	90x110x195	czyste 6mm	88,7-90,2	108,5-110	80	195	87,7-89,2	107,2-108,7
K-1844	1	90x120x195	czyste 6mm	88,7-90,2	118,5-120	80	195	87,7-89,2	117,2-118,7
K-1845	1	100x70x195	czyste 6mm	98,7-100,2	68,5-70	90	195	97,7-99,2	67,2-68,7
K-1846	1	100x80x195	czyste 6mm	98,7-100,2	78,5-80	90	195	97,7-99,2	77,2-78,7
K-1847	1	100x90x195	czyste 6mm	98,7-100,2	88,5-90	90	195	97,7-99,2	87,2-88,7
K-1848	1	100x100x195	czyste 6mm	98,7-100,2	98,5-100	90	195	97,7-99,2	97,2-98,7
K-1849	1	100x110x195	czyste 6mm	98,7-100,2	108,5-110	90	195	97,7-99,2	107,2-108,7
K-1850	1	100x120x195	czyste 6mm	98,7-100,2	118,5-120	90	195	97,7-99,2	117,2-118,7

* X1, X2 - WYMIAR DO OSI SZYB

TABELA ROZMIARÓW:

COPPER BRUSHED

SYMBOL	DRZWI	WYMIAR	SZKŁO	A	B	W	H	X1*	X2*
K-2281	1	70x70x195	czyste 6mm	68,7-70,2	68,5-70	60	195	67,7-69,2	67,2-68,7
K-2282	1	70x80x195	czyste 6mm	68,7-70,2	78,5-80	60	195	67,7-69,2	77,2-78,7
K-2283	1	70x90x195	czyste 6mm	68,7-70,2	88,5-90	60	195	67,7-69,2	87,2-88,7
K-2284	1	70x100x195	czyste 6mm	68,7-70,2	98,5-100	60	195	67,7-69,2	97,2-98,7
K-2285	1	70x110x195	czyste 6mm	68,7-70,2	108,5-110	60	195	67,7-69,2	107,2-108,7
K-2286	1	70x120x195	czyste 6mm	68,7-70,2	118,5-120	60	195	67,7-69,2	117,2-118,7
K-2287	1	80x70x195	czyste 6mm	78,7-80,2	68,5-70	70	195	77,7-79,2	67,2-68,7
K-2288	1	80x80x195	czyste 6mm	78,7-80,2	78,5-80	70	195	77,7-79,2	77,2-78,7
K-2289	1	80x90x195	czyste 6mm	78,7-80,2	88,5-90	70	195	77,7-79,2	87,2-88,7
K-2290	1	80x100x195	czyste 6mm	78,7-80,2	98,5-100	70	195	77,7-79,2	97,2-98,7
K-2291	1	80x110x195	czyste 6mm	78,7-80,2	108,5-110	70	195	77,7-79,2	107,2-108,7
K-2292	1	80x120x195	czyste 6mm	78,7-80,2	118,5-120	70	195	77,7-79,2	117,2-118,7
K-2293	1	90x70x195	czyste 6mm	88,7-90,2	68,5-70	80	195	87,7-89,2	67,2-68,7
K-2294	1	90x80x195	czyste 6mm	88,7-90,2	78,5-80	80	195	87,7-89,2	77,2-78,7
K-2295	1	90x90x195	czyste 6mm	88,7-90,2	88,5-90	80	195	87,7-89,2	87,2-88,7
K-2296	1	90x100x195	czyste 6mm	88,7-90,2	98,5-100	80	195	87,7-89,2	97,2-98,7
K-1975	1	90x110x195	czyste 6mm	88,7-90,2	108,5-110	80	195	87,7-89,2	107,2-108,7
K-1976	1	90x120x195	czyste 6mm	88,7-90,2	118,5-120	80	195	87,7-89,2	117,2-118,7
K-1977	1	100x70x195	czyste 6mm	98,7-100,2	68,5-70	90	195	97,7-99,2	67,2-68,7
K-1978	1	100x80x195	czyste 6mm	98,7-100,2	78,5-80	90	195	97,7-99,2	77,2-78,7
K-1979	1	100x90x195	czyste 6mm	98,7-100,2	88,5-90	90	195	97,7-99,2	87,2-88,7
K-1980	1	100x100x195	czyste 6mm	98,7-100,2	98,5-100	90	195	97,7-99,2	97,2-98,7
K-1981	1	100x110x195	czyste 6mm	98,7-100,2	108,5-110	90	195	97,7-99,2	107,2-108,7
K-1982	1	100x120x195	czyste 6mm	98,7-100,2	118,5-120	90	195	97,7-99,2	117,2-118,7

* X1, X2 - WYMIAR DO OSI SZYB

TABELA ROZMIARÓW:

GUNMETAL BRUSHED

SYMBOL	DRZWI	WYMIAR	SZKŁO	A	B	W	H	X1*	X2*
K-2125	1	70x70x195	czyste 6mm	68,7-70,2	68,5-70	60	195	67,7-69,2	67,2-68,7
K-2126	1	70x80x195	czyste 6mm	68,7-70,2	78,5-80	60	195	67,7-69,2	77,2-78,7
K-2127	1	70x90x195	czyste 6mm	68,7-70,2	88,5-90	60	195	67,7-69,2	87,2-88,7
K-2128	1	70x100x195	czyste 6mm	68,7-70,2	98,5-100	60	195	67,7-69,2	97,2-98,7
K-2129	1	70x110x195	czyste 6mm	68,7-70,2	108,5-110	60	195	67,7-69,2	107,2-108,7
K-2130	1	70x120x195	czyste 6mm	68,7-70,2	118,5-120	60	195	67,7-69,2	117,2-118,7
K-2131	1	80x70x195	czyste 6mm	78,7-80,2	68,5-70	70	195	77,7-79,2	67,2-68,7
K-2132	1	80x80x195	czyste 6mm	78,7-80,2	78,5-80	70	195	77,7-79,2	77,2-78,7
K-2133	1	80x90x195	czyste 6mm	78,7-80,2	88,5-90	70	195	77,7-79,2	87,2-88,7
K-2134	1	80x100x195	czyste 6mm	78,7-80,2	98,5-100	70	195	77,7-79,2	97,2-98,7
K-2135	1	80x110x195	czyste 6mm	78,7-80,2	108,5-110	70	195	77,7-79,2	107,2-108,7
K-2136	1	80x120x195	czyste 6mm	78,7-80,2	118,5-120	70	195	77,7-79,2	117,2-118,7
K-2137	1	90x70x195	czyste 6mm	88,7-90,2	68,5-70	80	195	87,7-89,2	67,2-68,7
K-2138	1	90x80x195	czyste 6mm	88,7-90,2	78,5-80	80	195	87,7-89,2	77,2-78,7
K-2139	1	90x90x195	czyste 6mm	88,7-90,2	88,5-90	80	195	87,7-89,2	87,2-88,7
K-2140	1	90x100x195	czyste 6mm	88,7-90,2	98,5-100	80	195	87,7-89,2	97,2-98,7
K-2141	1	90x110x195	czyste 6mm	88,7-90,2	108,5-110	80	195	87,7-89,2	107,2-108,7
K-2142	1	90x120x195	czyste 6mm	88,7-90,2	118,5-120	80	195	87,7-89,2	117,2-118,7
K-2143	1	100x70x195	czyste 6mm	98,7-100,2	68,5-70	90	195	97,7-99,2	67,2-68,7
K-2144	1	100x80x195	czyste 6mm	98,7-100,2	78,5-80	90	195	97,7-99,2	77,2-78,7
K-2145	1	100x90x195	czyste 6mm	98,7-100,2	88,5-90	90	195	97,7-99,2	87,2-88,7
K-2146	1	100x100x195	czyste 6mm	98,7-100,2	98,5-100	90	195	97,7-99,2	97,2-98,7
K-2147	1	100x110x195	czyste 6mm	98,7-100,2	108,5-110	90	195	97,7-99,2	107,2-108,7
K-2148	1	100x120x195	czyste 6mm	98,7-100,2	118,5-120	90	195	97,7-99,2	117,2-118,7

* X1, X2 - WYMIAR DO OSI SZYB